会社名 株式会社デービー精工 代表者名 代表取締役社長 小岩 満 問合せ先 総務部長 参輪 裕司 (TEL 079-232-9034)

当社香寺工場における IATF16949 認証の一時停止に関する件

株式会社デービー精工は、品質不適切行為(2023 年 4 月 14 日に三菱電機株式会社が公表)の判明を受け、認証機関であるビューローベリタスジャパン株式会社から、当社の香寺工場(及び豊富分工場)における IATF16949 認証 *1 を 10 月 2 日付で一時停止 *2 する旨の通知を受領しましたのでお知らせします。一時停止の概要は下記のとおりです。

お客様や関係者の皆様に多大なるご迷惑をお掛けしていることを、あらためてお詫び申し上げます。 当社は今後、今回の一時停止措置の早期解除に向けて全力で取り組んでまいります。

- ※1 自動車産業の品質マネジメントシステムに関する国際規格
- ※2 認証不適合の是正処置とその有効性を判断するまでの一時的な状態であり、一時停止期間中も認証は有効

記

- 1. 一時停止された認証規格 IATF 16949:2016
- 2. 登録番号

IATF 16949 - 422284 (香寺工場及び豊富分工場)

 認証の一時停止日 2023 年 10 月 2 日

以上

DB Seiko Co., Ltd. 1127 Mizoguchi, Kodera-cho, Himeji-shi, Hyogo, 679-2161, Japan

IATF16949 Certification for DB Seiko's Kodera Plant Temporarily Suspended

October 11, 2023 – DB Seiko Co., Ltd announced that the IATF16949 certifications for the company's Kodera Plant (included Toyotomi Plant as extended site) has been temporarily suspended by Bureau Veritas Japan Co., Ltd., effective October 2, in connection with the certain quality-related conduct at Kodera Plant, as announced by Mitsubishi Electric Corporation on April 14.

DB Seiko is currently taking corrective actions to enable the certifications to be promptly reinstated.

The IATF 16949 certification (IATF16949:2016; registration number IATF16949 – 422284) is an international standard for automotive quality management systems.

In accordance with the IATF protocols, certificate suspension is a temporary status which may result in either the reinstatement or withdrawal of the certificate. During the suspension period, the certificate remains valid and is still recognized by the IATF.